3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66441

Inspection Report

7208 Seminole Drive - COBI Project Name: Date: 04/11/2016 Any any 7208 Seminole Drive - COBI , Belle Isle, Orange County, FL Address: Permit No: 2016-03-048 Client: Lot No.: City of Belle Isle ProjectNo.: 0115.1400112.0000-0115-06 Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW zoning approved SFR plans

Maut B Rush

Inspection Type: Building Insulation

Disposition of Inspection: Pass as Noted

Comments:

Task DateTask NoteUser Name04/11/2016Need safety glazing in 2nd floor bathrooms. Will verify in field.Matthew Rush

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Matthew Rush, BN5145