



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66545

Inspection Report

Project Name: 7454 Daetwyler Drive (Lot 1) ~ COBI Ramos Residence

Date: 04/13/2016 Any any

Address: 7454 Daetwyler Drive (Lot 1) ~ COBI ,Belle Isle, Orange
County, FL

Permit No: 2016-02-040

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500050.0000-0115-06

Contact: Jack Meier at 407-948-2379

Scope of Inspection: Pool Steel & Ground Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498