3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66676

Inspection Report

Project Name: 7454 Daetwyler Drive (Lot 1) ~ COBI Ramos ResidenceDate: 04/15/2016 Any anyAddress: 7454 Daetwyler Drive (Lot 1) ~ COBI ,Belle Isle, Orange County, FLPermit No: 2016-03-051Client: City of Belle IsleLot No.:ProjectNo.: 0115.1500050.0000-0115-10Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW revision to add one more dryer vent for total of 2 dryer vents

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Matthew Rush, BN5145

Marie B Rush