



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66841

## Inspection Report

Project Name: 7454 Daetwyler Drive (Lot 1) ~ COBI Ramos Residence

Date: 04/26/2016 Any any

Address: 7454 Daetwyler Drive (Lot 1) ~ COBI, Belle Isle, Orange  
County, FL

Permit No: 2016-03-051

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500050.0000-0115-10

Contact: Christy Werkeiser at 407-294-  
6324

Scope of Inspection: Rough Mechanical Inspection

Inspection Type: **Mechanical - Rough In**

Disposition of Inspection: **Fail**

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/27/2016	Per Jim: no duct drawing on-site.	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: James Pappalardo, BN5706