

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 66949

Inspection Report

Project Name: 7454 Daetwyler Drive (Lot 1) ~ COBI Ramos Residence			Date:	04/26/2016 Any any
Address:	7454 Daetwyler Drive (Lot 1) ~ COBI, Belle Isle, Orange County, FL		Permit No:	2016-12-021
Client:	City of Belle Isle		Lot No.:	_
ProjectNo.:	0115.1	500050.0000-0115-05	Contact:	Rebecca Baldwin at 407.294.8900
Scope of Inspection: Tub Set Inspection				
Inspection Type:		See Scope		

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector:

James Pappalardo, BN5706

James & Vappalardo