

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80623

Date:	04/20/2017 Any any
Permit No:	2017-04-048
Lot No.:	
Contact:	Ivelinda Diaz at 407 282-2900
	Permit No: Lot No.:

Disposition of Inspection: Fail

Comments:		
Task Date	Task Note	<u>User Name</u>
04/21/2017	Per Les: no water in stack; leak may be in building drain in right rear room. FBC R P2503.4 AND 2503.5	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector:

Les Rutherford, BN 4564