



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 79818

Inspection Report

Project Name: 1432 Belle Vista Drive ~ COBI
Address: 1432 Belle Vista Drive ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1600223.0000-0115-05

Date: 03/31/2017 Any any
Permit No: 2017-03-089
Lot No.:
Contact: Joe and Teresa Gulino at 321-200-4489

Scope of Inspection: Final Plumbing Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564