



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80123

## Inspection Report

Project Name: 1616 Wind Harbor Road - COBI

Address: 1616 Wind Harbor Road - COBI, Belle Isle, Orange County, FL 32812

Client: City of Belle Isle

ProjectNo.: 0115.1300247.0000-0115-02

Scope of Inspection: Final Building Inspection for garage door

Inspection Type: See Scope

Date: 04/10/2017 Any pm

Permit No: 2017-04-020

Lot No.:

Contact: Gary Thurmond at 407-267-1953

Disposition of Inspection: Fail

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/10/2017	Per Les: Onsite 1245pm for pm inspection; no one home. FBC 110.1	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564