



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80551

Inspection Report

Project Name: 1616 Wind Willow Road - COBI

Date: 04/24/2017 Any any

Address: 1616 Wind Willow Road - COBI , Belle Isle, Orange County,
FL 32812

Permit No: 2017-04-020

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1300247.0000-0115-02

Contact: Gary Thurmond at 407-267-1953

Scope of Inspection: Final Building Re-inspection for Garage Door

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564