



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 81039

## Inspection Report

Project Name: 1679 Colleen Drive ~ COBI  
Address: 1679 Colleen Drive ~ COBI, Belle Isle, Orange County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1600325.0000-0115-01

Date: 04/27/2017 Any am  
Permit No: 2016-05-038  
Lot No.:  
Contact: Samantha Schmidt at 407-250-6768

Scope of Inspection: In-Progress Window Installation Inspection

Inspection Type: See Scope

Disposition of Inspection: Cancel

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/27/2017	Duplicate work order - permit was issued for a Door, not a Window.	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564