



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80929

Inspection Report

Project Name: 1903 Hoffner Avenue ~ COBI
Address: 1903 Hoffner Avenue ~ COBI , Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700137.0000-0115-01

Date: 04/24/2017 Any am
Permit No: 2017-04-012
Lot No.:
Contact: Clarence Hoenstine at 321-689-3346

Scope of Inspection: Final Building Inspection for shed

Inspection Type: **See Scope**

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564