



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 79875

## Inspection Report

Project Name: 2320 Homewood Drive ~ COBI

Date: 04/03/2017 Any any

Address: 2320 Homewood Drive ~ COBI, Belle Isle, Orange County,  
FL

Permit No: 2017-01-041

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501541.0000-0115-10

Contact: Joe Chuparkoff at 407.948.3676

Scope of Inspection: Underground Plumbing Inspection for pool

Inspection Type: See Scope

Disposition of Inspection: Pass

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564