



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80264

Inspection Report

Project Name: 2320 Homewood Drive ~ COBI
Address: 2320 Homewood Drive ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1501541.0000-0115-07
Scope of Inspection: Final Roof Inspection
Inspection Type: See Scope

Date: 04/12/2017 Any any
Permit No: 2017-12-034
Lot No.:
Contact: Katlynn Kellum at 321.441.2300

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564