



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80426

## Inspection Report

Project Name: 2816 Montmart Drive ~ COBI

Date: 04/14/2017 Any am

Address: 2816 Montmart Drive ~ COBI, Belle Isle, Orange County, FL

Permit No: 2017-03-046

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700053.0000-0115-02

Contact: Brian Stehli at 407-850-0846

Scope of Inspection: Final Building Inspection for solar panels

Inspection Type: **See Scope**

**Disposition of Inspection: Pass**

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564