



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 79685

Inspection Report

Project Name: 3007 Trentwood Blvd ~ COBI

Date: 03/31/2017 Any any

Address: 3007 Trentwood Blvd ~ COBI, Belle Isle, Orange County, FL

Permit No: 2017-03-100

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600458.0000-0115-05

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW electrical permit app for boat dock

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
03/31/2017	Provide electrical plan	Susan Manchester

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Joseph Crum, BU 540