



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80158

## Inspection Report

Project Name: 3307 Trentwood Blvd - COBI

Address: 3307 Trentwood Blvd - COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1300688.0000-0115-09

Date: 04/11/2017 Any any

Permit No: 2017-11-027

Lot No.:

Contact: Indira Gonzalez-Rosas at 407-809-5311

Scope of Inspection: Final Building Inspection for Windows

Inspection Type: **See Scope**

**Disposition of Inspection: Pass**

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564