



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 79887

Inspection Report

Project Name: 3525 Admiralty Court ~ COBI

Address: 3525 Admiralty Court ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1700121.0000-0115-01

Scope of Inspection: Final Roof Inspection

Inspection Type: **See Scope**

Date: 04/04/2017 Any any

Permit No: 2017-03-075

Lot No.:

Contact: Cynthia Waters at 407-423-7570

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564