3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80072

Inspection Report

Project Name: 3606 Quando Drive ~ COBI Date: 04/07/2017 Any any Address: 3606 Quando Drive ~ COBI, Belle Isle, Orange County, FL Permit No: 2017-02-017 Client: Lot No .: City of Belle Isle ProjectNo.: Contact: Samantha Schmidt at 407-250-0115.1700049.0000-0115-01 6768

Scope of Inspection: Final Building Inspection for Windows

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498

Karl E. Ma Gun