



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 79779

## Inspection Report

Project Name: 4118 Isle Vista Avenue ~ COBI

Date: 03/31/2017 Any any

Address: 4118 Isle Vista Avenue ~ COBI, Belle Isle, Orange County,  
FL

Permit No: 2017-12-032

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600228.0000-0115-03

Contact: John Carr at 407-947-5400

Scope of Inspection: Framing Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564