



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80303

Inspection Report

Project Name: 4124 Isle Vista Avenue ~ COBI

Date: 04/14/2017 Any any

Address: 4124 Isle Vista Avenue ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2017-03-091

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400381.0000-0115-13

Contact: Susan Manchester at 407 81 8161

Scope of Inspection: Pickup zoning-approved pool permit packet from 1600 Nela Ave and deliver to Susan at UES Maggie Blvd

Inspection Type: **See Scope**

Disposition of Inspection: Complete

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Lisa Whaley, 153187