



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80464

## Inspection Report

Project Name: 4124 Kandra Drive ~ COBI  
Address: 4124 Kandra Drive ~ COBI, Belle Isle, Orange County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1500624.0000-0115-03

Date: 04/14/2017 Any any  
Permit No: 2017-04-050  
Lot No.:  
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW building permit app for shed

Inspection Type: See Scope

Disposition of Inspection: Fail

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/17/2017	Per Joe: 1. Please provide a connector for the roof rafter to ride beam connection. 2. For the window – please complete and submit the FL Product Approval form with the manufactured window info. If the window is to be constructed on site – please provide the construction and connection details and thickness of the plexi-glass. 3. A separate roof permit is required for this project, a roof permit app has been attached for your use. Please include another copy of the Product Approval Form with the roof app with the PA numbers for the shingles as well as the underlayment.	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Joseph Crum, BU 540