



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80979

Inspection Report

Project Name: 4124 Kandra Drive ~ COBI

Address: 4124 Kandra Drive ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1500624.0000-0115-03

Date: 04/25/2017 Any any

Permit No: 2017-04-050

Lot No.:

Contact: Susan Manchester at 407 581
8161

Scope of Inspection: REVIEW new building info that arrived stamped 04.21.2017 to address noted deficiencies

Inspection Type: **See Scope**

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Joseph Crum, BU 540