



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 79816

Inspection Report

Project Name: 4149 Bell Tower Court ~ COBI

Date: 03/31/2017 Any am

Address: 4149 Bell Tower Court ~ COBI, Belle Isle, Orange County, FL

Permit No: 2017-02-044

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700044.0000-0115-02

Contact: Chris and Tracy Grubman at 407-855-2458

Scope of Inspection: Lintel inspection

Inspection Type: **See Scope**

Disposition of Inspection: Partial Pass

Comments:

Task Date

Task Note

User Name

03/31/2017

Per Les this is a Lintel inspection and two inspections are needed therefore this is a partial pass. A second lintel inspection is needed on the header over the side openings on either side where the sliding glass door was removed.

Susan Manchester

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564