



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 79929

Inspection Report

Project Name: 4149 Bell Tower Court ~ COBI

Date: 04/04/2017 Any am

Address: 4149 Bell Tower Court ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2017-02-044

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700044.0000-0115-02

Contact: Chris and Tracy Grubman at (407)
255-9978

Scope of Inspection: Lintel Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564