



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80276

Inspection Report

Project Name: 5015 Saint Michael Avenue ~ COBI

Address: 5015 Saint Michael Avenue ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1700102.0000-0115-01

Scope of Inspection: Final Roof Re-inspection

Inspection Type: See Scope

Date: 04/13/2017 Any any

Permit No: 2017-03-051

Lot No.:

Contact: Jessica Graf at (407) 851-0680

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/13/2017	Per Les: NO permit or product approvals on site; second fail. FBC 105.7 & FBC 107.3.1	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564