



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80547

Inspection Report

Project Name: 5018 Saint Denis Ct ~ COBI
Address: 5018 Saint Denis Ct ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700037.0000-0115-03
Scope of Inspection: Rough Electrical Inspection
Inspection Type: **See Scope**

Date: 04/18/2017 Any any
Permit No: 2017-03-068
Lot No.:
Contact: Lynette Singer at 407-568-0111

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564