3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80541

## **Inspection Report**

Project Name:5018 Saint Denis Ct ~ COBIDate:04/18/2017 Any anyAddress:5018 Saint Denis Ct ~ COBI, Belle Isle, Orange County, FLPermit No:2017-04-047Client:City of Belle IsleLot No.:ProjectNo.:0115.1700037.0000-0115-04Contact:Lynette Singer at 407-568-0111

Scope of Inspection: Underground Plumbing Inspection

Inspection Type: See Scope

**Disposition of Inspection:** Pass

## **Comments:**

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564