



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 81009

Inspection Report

Project Name: 5018 Saint Denis Ct ~ COBI

Address: 5018 Saint Denis Ct ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1700037.0000-0115-01

Scope of Inspection: Framing Inspection

Inspection Type: See Scope

Date: 04/26/2017 Any am

Permit No: 2017-01-081

Lot No.:

Contact: Keith Hastings at 4074688294

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/27/2017	PER LES: INTERIOR FRAMING ONLY NO EXTERIOR WALLS OR ROOF STRUCTURE (EXISTING).	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564