



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80151

Inspection Report

Project Name: 5026 Saint Marie Avenue ~ COBI

Date: 04/10/2017 Any any

Address: 5026 Saint Marie Avenue ~ COBI, Belle Isle, Orange County, FL

Permit No: 2017-03-045

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501038.0000-0115-02

Contact: PAULA MCKINNON at 407-275-0705

Scope of Inspection: Final Mechanical Inspection

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/10/2017	Per Les: no permit on site. FBC 105.7	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564