



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80221

Inspection Report

Project Name: 5109 Pleasure Island Road ~ COBI

Date: 04/13/2017 Any pm

Address: 5109 Pleasure Island Road ~ COBI, Belle Isle, Orange
County, FL

Permit No: 2017-04-026

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700146.0000-0115-01

Contact: Dorene Penhaligon at
407.265.2215

Scope of Inspection: Roof Deck Nailing / Dry-in / Flashing Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564