



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80639

## Inspection Report

Project Name: 5119 Darden Avenue ~ COBI

Date: 04/20/2017 Any pm

Address: 5119 Darden Avenue ~ COBI, Belle Isle, Orange County, FL

Permit No: 2017-04-013

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600543.0000-0115-02

Contact: Nils Bossen at 321-245-0267

Scope of Inspection: Final Demo Inspection for carport (to close out old expired OC permit B08010611)

Inspection Type: **See Scope**

**Disposition of Inspection: Pass**

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564