



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80206

Inspection Report

Project Name: 5245 Oak Island Road ~ COBI

Date: 04/11/2017 Any any

Address: 5245 Oak Island Road ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-09-039

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600497.0000-0115-01

Contact: Tim Kidd at 407-234-1320

Scope of Inspection: Ceiling Insulation Inspection (Final)

Inspection Type: **See Scope**

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564