



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 81008

## Inspection Report

Project Name: 5245 Oak Island Road ~ COBI

Address: 5245 Oak Island Road ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600497.0000-0115-01

Scope of Inspection: Driveway Approach Inspection

Inspection Type: **See Scope**

Date: 04/26/2017 Any any

Permit No: 2016-09-039

Lot No.:

Contact: Tim Kidd at 407-234-1320

**Disposition of Inspection:** Pass

**Comments:**

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564