



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80118

## Inspection Report

Project Name: 5700 Cove Drive ~ COBI  
Address: 5700 Cove Drive ~ COBI, Belle Isle, Orange County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1501272.0000-0115-02

Date: 04/07/2017 Any any  
Permit No: 2017-04-023  
Lot No.:  
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW electrical permit app to re-route elec to bypass old garage that will be demo'd and instead run underground from house panel directly to boat dock and irrigation pump.

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927