



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 81015

## Inspection Report

Project Name: 5842 Cove Drive ~ COBI

Address: 5842 Cove Drive ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600508.0000-0115-01

Scope of Inspection: Footer Inspection

Inspection Type: See Scope

Date: 04/26/2017 Any any

Permit No: 2016-09-053

Lot No.:

Contact: Jeffrey Giles at 407-509-8309

Disposition of Inspection: Partial Pass

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/27/2017	Per Les: rear four pads only - two visits to site needed, front pads incomplete.	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564