



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80532

## Inspection Report

Project Name: 6509 Matchett Road ~ COBI  
Address: 6509 Matchett Road ~ COBI, Belle Isle, Orange County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1700126.0000-0115-01  
Scope of Inspection: Final Building Inspection for doors.  
Inspection Type: **See Scope**

Date: 04/18/2017 Any any  
Permit No: 2017-03-087  
Lot No.:  
Contact: Leslie Tischler at 407-273-0078

**Disposition of Inspection: Pass**

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564