



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 81003

## Inspection Report

Project Name: 6557 Gibson Drive ~ COBI

Address: 6557 Gibson Drive ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1700154.0000-0115-01

Date: 04/25/2017 Any any

Permit No: 2017-04-045

Lot No.:

Contact: Susan Manchester at 407 581  
8161

Scope of Inspection: REVIEW building permit app for boat dock - zoning has been approved

Inspection Type: See Scope

**Disposition of Inspection: Pass**

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Joseph Crum, BU 540