



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 79944

Inspection Report

Project Name: 6606 Conway Lakes Drive ~ COBI

Address: 6606 Conway Lakes Drive ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600489.0000-0115-03

Scope of Inspection: Final Building Inspection for boat dock

Inspection Type: See Scope

Date: 04/05/2017 Any pm

Permit No: 2017-01-010

Lot No.:

Contact: Kyle Vanvelzen at 407.963.4489

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/05/2017	Per Les - requested PM inspection. Arrived on property at 12:40 pm. Only the building permit card was in the box - the EPA docs as well as dock building plans were not in the box. Knocked on door of house - no one answered. Boat dock plans, EPA doc and finalized survey indicating dock is in the location approved must accompany the building permit card. Fail as per FBC 110.5.	Susan Manchester

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564