



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 79946

Inspection Report

Project Name: 6606 Conway Lakes Drive ~ COBI
Address: 6606 Conway Lakes Drive ~ COBI, Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1600489.0000-0115-05
Scope of Inspection: Final Electrical Inspection for boat dock
Inspection Type: See Scope

Date: 04/05/2017 Any pm
Permit No: 2017-01-012
Lot No.:
Contact: Kyle Vanvelzen at 407.963.4489

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564