



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80452

Inspection Report

Project Name: 6609 Saint Partin Place ~ COBI
Address: 6609 Saint Partin Place ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700149.0000-0115-01
Scope of Inspection: Roof Deck Nailing / Dry-in / Flashing Inspection
Inspection Type: See Scope

Date: 04/18/2017 Any am
Permit No: 2017-04-039
Lot No.:
Contact: Ashlee Lemons at 321-441-2300

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564