



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80231

Inspection Report

Project Name: 6619 Matchett Road ~ COBI

Address: 6619 Matchett Road ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1700147.0000-0115-01

Date: 04/14/2017 Any any

Permit No: 2017-04-027

Lot No.:

Contact: Susan Manchester at 407 581
8161

Scope of Inspection: REVIEW building permit app for kitchen remodel including s/s plans to remove load bearing wall, new doors & windows

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Joseph Crum, BU 540