



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80394

## Inspection Report

Project Name: 6619 Matchett Road ~ COBI  
Address: 6619 Matchett Road ~ COBI, Belle Isle, Orange County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1700147.0000-0115-03

Date: 04/14/2017 Any any  
Permit No: 2017-04-041  
Lot No.:  
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW plumbing permit app

Inspection Type: See Scope

Disposition of Inspection: Fail

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/18/2017	Needs plumbing piping plan and layout per Joe Crum	Susan Manchester

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Joseph Crum, BU 540