



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 79916

Inspection Report

Project Name: 6723 Matchett Road ~ COBI

Address: 6723 Matchett Road ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1400449.0000-0115-05

Scope of Inspection: Underground Electrical Inspection

Inspection Type: See Scope

Date: 04/04/2017 Any any

Permit No: 2016-11-005

Lot No.:

Contact: Connie Young at 407-859-3400

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/04/2017	Per Les: inspection passed; print this report & place in the permit box with the approved extension app.	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564