



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80357

Inspection Report

Project Name: 6723 Matchett Road ~ COBI
Address: 6723 Matchett Road ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1400449.0000-0115-16

Date: 04/14/2017 Any any
Permit No: 2017-03-102
Lot No.:
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW new info that arrived to satisfy Joe's deficiencies for boathouse electrical permit app

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/17/2017	Per Joe: pass as noted on plans.	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Joseph Crum, BU 540