



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80154

Inspection Report

Project Name: 7224 Conway Circle ~ COBI

Date: 04/10/2017 Any any

Address: 7224 Conway Circle ~ COBI, Belle Isle, Orange County, FL

Permit No: 2017-03-101

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1700131.0000-0115-01

Contact: Elena Hume at 407-617-1056

Scope of Inspection: Rough Demolition Inspection for pool

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/10/2017	Per Les: final will be needed once filled and graded; rough was for confirming bottom punched out.	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564