



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80511

Inspection Report

Project Name: 7224 Conway Circle ~ COBI
Address: 7224 Conway Circle ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700131.0000-0115-01
Scope of Inspection: Final Pool Demolition Inspection
Inspection Type: See Scope

Date: 04/18/2017 Any am
Permit No: 2017-03-101
Lot No.:
Contact: Elena Hume at 407-617-1056

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564