



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 79813

## Inspection Report

Project Name: 7454 Daetwyler Drive (Lot 1) ~ COBI Ramos Residence

Date: 03/31/2017 Any am

Address: 7454 Daetwyler Drive (Lot 1) ~ COBI, Belle Isle, Orange  
County, FL

Permit No: 2017-02-028

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1500050.0000-0115-16

Contact: Claire Cordova at 407-913-3246

Scope of Inspection: Final Building Inspection for pool

Inspection Type: See Scope

Disposition of Inspection: Fail

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
03/31/2017	Not Ready FBC 110.5	Susan Manchester

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564