



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80209

Inspection Report

Project Name: 7902 Daetwyler Drive ~ COBI

Date: 04/11/2017 Any am

Address: 7902 Daetwyler Drive ~ COBI, Belle Isle, Orange County, FL

Permit No: 2017-10-028

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400010.0000-0115-13

Contact: Brent Krueger at 3214366595

Scope of Inspection: Final Mechanical Inspection

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/11/2017	Per Les: not ready; no breakers in panel-FBC 110.5. Also, no notice on panel re attic equipment location- FBC ER403.6.1.	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564