



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80262

## Inspection Report

Project Name: 7902 Daetwyler Drive ~ COBI

Address: 7902 Daetwyler Drive ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1400010.0000-0115-11

Scope of Inspection: Final Building Inspection for boat dock

Inspection Type: See Scope

Date: 04/12/2017 Any any

Permit No: 2016-09-041

Lot No.:

Contact: Matt Langebehn at 407-583-6251

Disposition of Inspection: Fail

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
04/12/2017	Per Les: need final survey and permit on site. FBC 110.5	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Les Rutherford, BN 4564