



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 80116

Inspection Report

Project Name: Lot 1 - 3500 Brighton Pk Cir ~ COBI Bldg 16
Address: Lot 1 - 3500 Brighton Park Circle ~ COBI, Belle Isle, Orange
County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1700009.0000-0115-03
Scope of Inspection: Brighton Park - Underground Plumbing Inspection
Inspection Type: See Scope

Date: 04/07/2017 Any pm
Permit No: 2017-04-006
Lot No.:
Contact: Gary Preston at (407) 590-4329

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498